

BASSETL. DISTRICT COUNC December 2012

## Document details

Title:	Listed Buildings at Risk in Bassetlaw 2012.
Summary:	This document provide service users with information about how redundant, vulnerable or decay historic buildings and a register of which buildings are currently regarded as being at risk by the Council.
Approved:	This document was approved by Planning Committee on 6 <sup>th</sup> February 2013 at Retford Town Hall. The document was published on 7 <sup>th</sup> February 2013.

#### Document availability:

Copies of the document are available at Bassetlaw District Council Planning Services and on the Council's website:

www.bassetlaw.gov.uk/

## Contents

1. INTRODUCTION	4
What is a Building at Risk?	6
What is a listed building?	6
What does a listed building grade indicate?	7
Why produce a Register?	7
What buildings are included in the Register?	8
When is a building taken off the Register?	9
What are the reasons for historic buildings being at risk?	9
How can the District Council ensure that buildings are being restored?	9
What help is available for owners of buildings at risk?	10
2. THE REGISTER	11
Key to the entries	11
Register entries	12
register entries	14
3. STRUCTURES REMOVED FROM THE REGISTER	77
4. REDUCING THE RISKS	89
5. ADDITIONAL INFORMATION	91
Useful contacts	92
Grants	93
Publications and guidance	93
Heritage at risk on the web	94
Contact us	95
Summary table of listed buildings at risk	95



# 1. Introduction

#### 1. Introduction

Bassetlaw District has over 1000 buildings, structures and monuments that are regarded to be of national significance and designated as *listed buildings*<sup>1</sup>. Whilst the great majority are in good condition, there are a number of buildings that have fallen into disuse and disrepair. These structures are commonly referred to as 'Buildings at Risk' (BaR). Nottinghamshire County Council has been carrying out condition surveys of vulnerable buildings since the 1980s. The County Council first published details of buildings at risk in the *Historic Buildings at Risk in Nottinghamshire 2004*<sup>2</sup>. The *Listed Buildings at Risk in Bassetlaw 2012* is an update of this publication.

English Heritage also publishes a register of nationally significant designated heritage at risk, including all Grade I and II\* structures<sup>3</sup>. Consequently, there is no need to replicate this in the local BaR Register.

The purpose of the Register is to raise awareness of the deteriorating condition of a number of listed buildings and to generate interest among the local community and potential investors. Listed buildings that are not being maintained in a reasonable condition can be subject to legal action by the Council to enforce proper repairs<sup>4</sup>. In the most extreme cases, neglect may lead to compulsory purchase proceedings by the council.

The Conservation Teams at both Nottinghamshire County Council and Bassetlaw District Council has been regularly involved in tackling heritage at risk and a number of structures are no longer regarded as being at risk. The methodology for assessing the buildings has also evolved alongside the national *Heritage at Risk Register*. A formal resurvey of all structures in the 2004 BaR publication has therefore been undertaken, and there are new inclusions as well as removals from the Register<sup>5</sup>. 63 listed buildings are included on the 2012 BaR update, accounting for 6.5% of the total Grade II structures in the District.

The assessment of each building/structure was predominantly based on an external inspection only. Due to logistical and resource practicalities, inspections were not

<sup>&</sup>lt;sup>1</sup> Listed buildings are identified for their special architectural and historic interest and are protected under the Planning (Listed Buildings and Conservation Areas) Act 1990. In December 2012, the up-to-date total number of listed buildings for Bassetlaw was 1057. The list is not static and will change as new buildings are added, or existing structures are amended or removed from the list.

<sup>&</sup>lt;sup>2</sup> This document included a comprehensive survey of Bassetlaw District, which indicated that 91 from a total of 1063 of Bassetlaw's listed buildings were at risk. This figure is 8.6% of the District's listed buildings and accounted for 27.3% of the entire County's BaR.

<sup>&</sup>lt;sup>3</sup> The national heritage at risk register can be accessed at: <u>http://www.english-heritage.org.uk/caring/heritage-at-risk/</u>. Grade II churches in active use as places of worship or structures that are also scheduled monuments might also be included on the national register.

<sup>&</sup>lt;sup>4</sup> As set out in the Planning (Listed Buildings and Conservation Areas) Act 1990.

<sup>&</sup>lt;sup>5</sup> These amendments to the Register are based upon officer knowledge of buildings that Council Officers have become aware of during the past 6 years, although the principal survey work was carried out between 2009 and 2012.

generally arranged with property owners and the survey was carried out by viewing sites from public land wherever practicable<sup>6</sup>.

This BaR update is not, however, the result of a total resurvey of all listed buildings in the District, and it is likely that further amendments will be made to the Register at regular intervals over the coming years.

It is anticipated that by highlighting vulnerable buildings, the Council can positively monitor and manage the historic environment and target resources to assist regeneration objectives<sup>7</sup>.

#### What is a Building at Risk?

The term 'Building at Risk' usually refers to a listed building that is suffering from neglect and decay. These structures are usually vacant, under used and/or decayed.

The term may also be used for other historic structures that are not identified as listed buildings but lie within a conservation area and are regarded to be positive. These will, however, be formally identified through an adopted conservation area appraisal and are therefore not included in this Register.

#### What is a listed building?

A listed building is historic structure that has been recognised nationally for its special architectural and/or historic interest and is included in a list compiled by the Government<sup>8</sup>. A listed building can be anything from a large country house to a milestone<sup>9</sup>.

When a building is listed, the designation includes the whole of the exterior and interior and any attached structures or extensions whether historic or recent.

Any buildings or structures within the curtilage or grounds of a listed building that originate from before 1<sup>st</sup> July 1948 may also be considered as listed<sup>10</sup>. These

<sup>&</sup>lt;sup>6</sup> Where access was not possible, the status of the property during the previous survey was taken into account when assessing the risk grade.

<sup>&</sup>lt;sup>7</sup> The Council's strategic aims for sustaining and enhancing the District's historic built environment are set out in the Local Development Framework Core Strategy and Development Management Policies Development Plan Document (adopted 2011). Strategic Objective 9 of the Core Strategy seeks to reduce the number of heritage assets at risk.

<sup>&</sup>lt;sup>a</sup> Listed buildings are protected by the Planning (Listed Buildings and Conservation Areas) Act 1990 ('the Act'). English Heritage has published technical notes on listing principles called *Listing Selection Guides*: <u>http://www.english-heritage.org.uk/caring/listing/criteria-for-protection/selection-guidelines/</u>.

<sup>&</sup>lt;sup>9</sup>The description for each listed building can be downloaded at: <u>http://list.english-heritage.org.uk/</u>.

<sup>&</sup>lt;sup>10</sup> See Section 1 (5) of the Act.

buildings or structures are often referred to as 'curtilage listings'. Any curtilage buildings or structures that are at risk are clearly denoted in the register.

A consequence of listing is that any works that may affect its special interest, internally or externally, will almost always require listed building consent from the local planning authority<sup>11</sup>.

#### What does a listed building grade indicate?

Listed buildings are identified by a 'grade'<sup>12</sup>. The grade indicates their relative importance:

- Grade I buildings are of exceptional interest, sometimes considered to be internationally important. Only 2.5% of all listed buildings are Grade I;
- Grade II\* buildings are particularly important buildings of more than special interest. Only 5.5% of listed buildings are Grade II\*;
- Grade II buildings are nationally important and of special interest; 92% of all listed buildings are in this class.

Only Grade II listed buildings are included on the Bassetlaw BaR Register. The condition of Grade I and Grade II\* buildings are monitored by English Heritage and are published in their annual 'Heritage at Risk Register'.

#### Why produce a Register?

The aim of the Register is to monitor the condition of Grade II listed building within the District and raise awareness of redundancy and/or decay in the historic environment. The Register can be used to prompt owners or members of the public to take action to get these buildings repaired and secure their long term future. The Register might also help to find new owners that are able to repair a building at risk.

Ultimately, the Register is a resource to assist decision-makers and listed building owners to set priorities for planning and financing building work, and to persuade funders to make money available for their repair<sup>13</sup>.

The Council's aim to reduce heritage at risk is set out in Strategic Objective 9 of the Local Development Framework Core Strategy. The Council will monitor the delivery of this objective in the Annual Monitoring Report.

<sup>&</sup>lt;sup>11</sup> Works that may affect the special interest of a listed building include any form of alteration or demolition. Advice should always be sought from the local planning authority before any works are considered. For more advice on listed buildings, follow the links to planning and conservation at: <u>http://www.bassetlaw.gov.uk/</u>.

<sup>&</sup>lt;sup>12</sup> The 1057 listed buildings in Bassetlaw consist of: 966 Grade II, 49 Grade II\* and 42 Grade I.

<sup>&</sup>lt;sup>13</sup> English Heritage, the local or county authority, amenity groups and/or building preservation trusts are most commonly involved in funding programmes.

### What buildings are included in the Register?

The Register includes buildings that have been identified as being 'at risk' by using a set of national criteria devised by English Heritage, the government's advisory body on heritage in England.

The risk level is determined by assessing the condition of a building (usually by external inspection only) and whether it is occupied or in use. The figure below shows how the risk level is determined by condition and occupancy. *Extreme risk* is the worst level and is determined by severe structural failure and redundancy. At the other end of the scale, buildings and structures that are in a fair or good structural condition may still warrant regular inspection due to their vacancy or lack of maintenance, both of which can lead to longer term problems.

Condition	Occupancy	Risk Level	
1. VERY BAD	0. NOT APPLICABLE	- 1A	Extreme Risk
Likely structural failure or substanial material loss.	1. VACANT 2. PARTIALLY OCCUPIED 3. OCCUPIED	2	Grave Risk
2. POOR	0. NOT APPLICABLE	- 3A	At Risk
Deterioration which may lead to structural failure.	1. VACANT 2. PARTIALLY OCCUPIED 3. OCCUPIED	>3	
3. FAIR	0. NOT APPLICABLE	- 4A	Vulnerable
Stucturally sound but	1. VACANT		(Buildings to watch)
lack of maintenance.	2. PARTIALLY OCCUPIED 3. OCCUPIED	5	maiony
4. GOOD	0. NOT APPLICABLE	- 5A	Buildings not
Structurally sound	1. VACANT		at Risk
and well maintained.	2. PARTIALLY OCCUPIED 3. OCCUPIED	6	

Assessment of risk, model adapted from English Heritage, Buildings at Risk – A Sample Survey (English Heritage, 1992). The letter 'A' refers to structures and monuments which cannot be occupied. Their risk level is determined by their condition only.



Structures that are classified as being at *extreme* or *grave* risk have a red traffic light symbol on the individual BaR entry.

Structures that are *at risk* have an amber traffic light symbol on the individual BaR entry.

The traffic light system is designed to highlight buildings and structures that are a priority for action due to their condition and vulnerability.

#### When is a building taken off the Register?

Buildings are removed from the Register once they have been repaired and are occupied or occupation is imminent. Buildings that are in the process of conversion and repair are technically still considered to be at risk and will remain on the Register until they are structurally sound and in a position to be well maintained.

#### What are the reasons for historic buildings being at risk?

There are some typical reasons why buildings can become neglected and disused, and often more than one factor is involved:

**Redundancy** - The building may no longer be suited to the function for which it was originally designed or is currently used for. Once a building is vacant and left unsecured it can become easily subject to decay, vandalism or arson.

**Ownership** - The owner lacks the means to keep the building in good repair. Some owners choose not to keep their building in a good state of repair; others refuse to sell it at a price that reflects its actual condition.

**Location** - The building lies within the curtilage of a larger building and/or access problems prevent a change of ownership. A building might also be seriously blighted by insensitive road schemes or its surroundings, for example, if it lies within an abandoned industrial area or an economically deprived area.

**Economic** - There is a disparity between the cost of repair and the end value of a building once repaired.

# How can the District Council ensure that buildings are being restored?

Listed building owners have, by implication, a responsibility to keep a building in a reasonable state of repair. There are a number of statutory powers available to the local planning authority to enforce the undertaking of works if a building falls into disrepair. These powers are usually employed as a last resort when attempts to encourage and to work in co-operation with the owner have failed.

**Urgent Works Notice** - Where there is an immediate danger to a building the local authority can carry out emergency repairs following an 'Urgent Works Notice'. The costs of these repairs can be re-covered from the owner. Urgent works are usually just a temporary measure, for example, to make the building secure against the elements or vandals, or to prevent it from collapsing.

**Repairs Notice** - Where a building is left to deteriorate the local authority can serve a 'Repairs Notice'. It will identify the work required to ensure a building's survival and also specify a timescale within which these repairs have to be carried out.

**Compulsory Purchase Order** - If an owner who has been served with a 'Repairs Notice' fails to take any action towards the building's preservation within a period of two months, the local authority, The Secretary of State or English Heritage has the powers to compulsory purchase the building following the serving of a 'Compulsory Purchase Order'. The owner will be forced to sell at a price that reflects the actual condition agreed by the district surveyor. The authority can then repair the building themselves. In most cases, however, the building doesn't remain in public ownership but is handed on to a private individual or body, which has the funds to carry out the necessary repairs.

#### What help is available for owners of buildings at risk?

The District Council's Conservation Team is always willing to offer advice to owners of buildings at risk, whether technical or in relation to funding opportunities<sup>14</sup>. The Council currently operates a small grant scheme to support works that secure the repair and regeneration of listed buildings on either the local or national BaR Register<sup>15</sup>.

There are funding bodies that can offer assistance to all grades of building<sup>16</sup>. Funding opportunities will often be linked with the use of a building. Community uses, charitable organisations or educational facilities, for example, are more likely to receive financial assistance than a private householder. However, owners of buildings at risk should never be discouraged from seeking financial assistance towards repairing their building.

For further information relating to grant aid, it is advisable to speak with the Council's Conservation Team and to read further information on the Council's website (<u>http://www.bassetlaw.gov.uk/</u>).

<sup>&</sup>lt;sup>14</sup> Although buildings at risk are a priority for both the local planning authority and English Heritage, repair grants are limited in relation to demand.

<sup>&</sup>lt;sup>15</sup> Any listed building not currently identified on the Buildings at Risk Register, which in the view of the Council has become immediately 'at risk' under the assessment criteria laid down by English Heritage, may be eligible for grant assistance. Contact the Conservation Team for more information.

<sup>&</sup>lt;sup>16</sup> Contact details for national amenity bodies potentially capable of specific grants are included in Appendix A.



# 2. The Register



#### 2. The Register

The Register includes entries of Grade II listed buildings considered to be at risk using the *assessment of risk* table on page 8.

#### Key to the entries

Each entry contains the following information:

#### **Building/structure name**

The statutory list description building/structure name is generally used to identify each entry. Name changes made through street names and numbering will usually be included in brackets.

#### Building at Risk reference no.

This is a two digit code. The order in the Register is alphabetical based upon parish/settlement location which is labelled below the reference number in the top left corner.

#### Image of structure

Photographs are taken by the Conservation Team, usually at the time of the last inspection.

#### **Designation type**

This confirms any national designations that apply, including listing and scheduling, or location within a conservation area and/or registered park and garden.

GII – Grade II listed SM – Scheduled Monument CA – Conservation Area P&G –Registered Park and Garden

#### Listed building reference

Includes all relevant unique reference numbers for the listed building, both nationally and locally.

#### **BaR survey dates**

Gives dates of site inspections by conservation officers.

#### Condition

The condition label corresponds with the assessment of risk table: good, fair, poor or very bad. The condition may relate only to the part of the site or structure that is at risk and not the whole site.

#### **Risk level**

Number between 1 and 6 that corresponds with risk assessment table. The lower the number, the greater the risk level. Extreme risk is level 1 and will usually relate to structures likely to collapse or significantly deteriorate and are vacant.



Structures that are classified as being at *extreme* or *grave* risk have a red traffic light symbol on the individual BaR entry.

Structures that are at risk have an amber traffic light symbol on the individual BaR entry.

#### Occupancy

Identifies whether the building is vacant, occupied or partially occupied. This will not be applicable to certain structures such as tomb stones (this is represented by an A after the number given on the risk level).

#### **Ownership**

If known, this will identify the type of ownership. Typically, ownership is private. Other types may include local authority or ecclesiastical.

#### Description

Indicative summary of special architectural and historic interest. This is generally taken from the list description, but may be edited for publication purposes<sup>17</sup>.

#### **Reasons for risk status**

Explanation for risk level using the assessment criteria. Discussion may include issues relating to the current usage of the building, as well as the condition of fabric, ongoing maintenance problems or security concerns.

#### **Relevant planning history**

Any active or recent applications that may have a bearing on the building's condition and/or future are referenced.

#### Previous risk level/change from 2004 BaR survey

The previous risk level is compared with the updated assessment. After the number, reference will be made to any change: deteriorated (has got worse since the last survey), improvement (has got better since the last survey) or no change. New entries are specified as not applicable.

<sup>&</sup>lt;sup>17</sup> The full list description can be accessed via the English Heritage website: <u>http://list.english-</u> heritage.org.uk/.

## BaR: 01 Beckingham

## **Pigeoncote and fodder store**

Pear Tree Farm, Gringley Road (A631), DN10 4QF

Designation type(s): GII

Listed building ref(s): UID: 241089 List entry number: 1370368 Local: 6/5

BaR survey date(s) 13/04/2005 01/07/2009

Condition: Fair

Occupancy: Partially occupied

Risk level:

4 – vulnerable (building to watch)

Ownership: Private



#### Description

Pigeoncote, built circa 1796. Red brick with clay pantile roof. First floor and eaves bands, stone lintels, cogged eaves and lintels, tumbled brick coped gables. 2 storeys, 3 bays. Central close boarded stable door flanked by flat brick buttresses, rising almost to eaves, spanned by cogged stone lintel. Above, 3 tiers of blocked brick pigeonholes and a further stone lintel. Right and left gables also have 2 tiers of pigeonholes. At rear, single storey lean-to fodder store. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

Currently used for storage. Roof repaired and rear fodder store rebuilt 2005. Crack in masonry above lintel (at string course) of front doorway. Overall, structure is sound but in need of repairs/maintenance.

#### **Relevant planning history**

Roof repairs and reconstruction works granted in 2005 (ref 06/05/00003/L). Scheme implemented.

#### Previous risk level/change from 2004 BaR survey

3 – improvement.

## BaR: 02 Blyth

# Memorial to Joseph Dymond

Church Yard of St Mary & St Martin Church

#### Designation type(s): GII Blyth CA

Listed building ref(s): UID: 416956 List entry number: 1273833 Local: 2/76

BaR survey date(s): 11/05/2012

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Memorial to Joseph Dymond. Late 18<sup>th</sup> century ashlar square plinth surmounted by obelisk, damaged at the top, and inscribed "In Memory of Joseph Dymond ....". Designated: 27 November 1984.

#### **Reasons for risk status**

Large cracks, much worn stonework.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3A – no change.

## BaR: 03 Blyth

## Gateway formerly to Blyth Hall

Sheffield Road

#### Designation type(s): GII Blyth CA

Listed building ref(s): UID: 416671 List entry number: 1238970 Local: 2/73

BaR survey date(s): 11/05/2012

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Unknown



#### Description

Gate piers, wall, gates and gate stones, c,1770. Ashlar and wrought iron. Rusticated and coped wall, set on a plinth, having central double wrought iron gates with decorative wrought iron overthrow and central bell over. The overthrow rests upon the wall. Flanking these gates are single, damaged, rusticated piers, protruding from and rising above the wall. These have a frieze decorated with paterae and a dentil cornice. Either side are single rusticated arches supported on imposts with a single wrought iron gate under and at the outer edges single rusticated piers terminating at the level of the wall. Designated: 30<sup>th</sup> November 1966.

#### **Reasons for risk status**

Stone damage around metal mounting joints.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3A – no change.

16

# Milestone 90m south of Ivy Cottages

## BaR: 04 Blyth

#### Sheffield Road

Designation type(s): GII

Listed building ref(s): UID: 416670 List entry number: 1239142 Local: 2/72

BaR survey date(s): 23/05/2012

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: County Council



#### Description

Milestone. Late 18<sup>th</sup> century. Ashlar. Triangular stone one metre high with inscriptions "Barnby Moor.... Miles" and "Maltby .... Rotherham 13 Miles.". Designated: 27<sup>th</sup> November 1984.

#### **Reasons for risk status**

In poor condition, severely eroded.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3A – no change.

## BaR: 05 Bothamsall

**Meadow Lane** 

## **Road bridge**



Designation type(s): GII

Listed building ref(s): UID: 491536 List entry number: 1391658 Local: 529/0/10006

BaR survey date(s): 15/05/2012

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Bridge, circa 1800 with later repairs. Red brick with stone dressings. Two round arches with a brick sill band, stone cutwaters, and stone parapet copings. Parapets slope down to end piers with shaped caps. This well-detailed bridge carries the road over the River Meden and appears on Sanderson's map, 1835. Designated: 28<sup>th</sup> April 2006.

#### **Reasons for risk status**

Partial collapse of parapet, fabric fallen into river. Masonry repairs needed. Vegetation is a problem.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

Ŏ

## BaR: 06 Carlton in Lindrick

# Lavin's Cottage and outbuilding

#### Church Lane, S81 9EH

Designation type(s): GII Carlton CA

## Listed building ref(s):

UID: 241366 List entry number: 1206347 Local: 4/10

BaR survey date(s): 15/05/2012

Condition: Poor

Occupancy: Partially occupied

Risk level: 3 – at risk

Ownership: Private



#### Description

Located near the parish church, this former public house, built in the mid-18th century, is built in coursed rubble with a pantile roof. Most of the openings are Yorkshire slider sash windows. The rear gable contains three rows of pigeon holes. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

Visible cracks in masonry, notably to external wall in south gable. East wall is bellying near south gable. Missing/slipped roof tiles. Vegetation to ridge and chimney stack at southern end of building. Missing/defective rainwater goods. Stone walls in need of repair/repointing. Pigeon infestation. Water ingress to first floors and signs of deterioration in lathe and plaster/gypsum floors (northern most bay of building). Partially used for storage by adjacent cottage.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3 – no change.

## BaR: 07 Carlton in Lindrick

# Barn and attached outbuildings at North House

The Green, S81 9AQ

Designation type(s): GII Carlton CA

## Listed building ref(s):

UID: 241380 List entry number: 1280211 Local: 4/24

BaR survey date(s): 22/09/2010

Condition: Poor

Occupancy: Partially occupied

Risk level: 3 – at risk

Ownership: Private



#### Description

Late 18<sup>th</sup>/early 19<sup>th</sup> century agricultural buildings. Dressed coursed rubble, pantile roofs, stone coping. Main barn has blocked carriage opening. Range has numerous timber slatted/glazing bar windows, with several timber slatted doors, the majority of which are under segmental arches. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

The main barn is showing signs of disrepair with missing tiles and evidence of small scale collapse in the corner of the roof. Much of the guttering is broken, several timber windows and doors untreated or damaged, signs of structural instability.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

## BaR: 08 Carlton in Lindrick

## Wigthorpe House

Wigthorpe House Lane, Wigthorpe, S81 8BT

#### Designation type(s): GII Carlton CA

### Listed building

UID: 241386 List entry number: 1206458 Local: 4/30

#### BaR survey date(s):

29/05/2008 29/03/2012 15/05/2012

Condition: Very bad

Occupancy:

Vacant

Risk level: 1 – extreme risk

Ownership: Private



#### Description

Mid-18<sup>th</sup> century house with 19<sup>th</sup> century extensions, making it an L-plan. Built of dressed coursed rubble with some rendering and slate roof. In the centre is an ashlar two storey bay window and a conservatory/greenhouse on the eastern end. Behind is a row of outbuildings. Designated: 30<sup>th</sup> November 1966.

#### **Reasons for risk status**

The house has been abandoned and lost its roof which, although temporarily protected, could lead to serious deterioration. The chimneys have collapsed through the roof. Much of the guttering has broken, leading to deterioration of the masonry. Doors are boarded up and windows are shuttered, although many are broken. Vegetation is increasingly becoming a serious problem, particularly on the back wing of the house.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

## BaR: 09 Church Laneham

## Manor Farm and attached wall

Church Lane, DN22 ONJ

#### Designation type(s): GII

Listed building ref(s): UID: 409019 List entry number: 1276573 Local: 2/28

BaR survey date(s): 18/05/2012

Condition: Fair

Occupancy: Not applicable

#### Risk level:

4A – vulnerable (building to watch)

Ownership: Private



#### Description

Farmhouse and attached wall. Early 19<sup>th</sup> century. Low red brick wall with ashlar coping surmounted by iron railings with decorative finials. This extends 4 metres west and then 44 metres north, broken by a small gateway with a pair of decorative iron piers and a similar gate. Designated: 12 July 1985.

#### **Reasons for risk status**

House is occupied but attached wall is considered to be vulnerable. Structurally sound, but lack of maintenance. Small number of individual vertical rails missing. Vegetation is a slight problem.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

1A – improvement.

## BaR: 10 Clarborough

# Pair of chest tombs 2 metres west of tower

St John the Baptist Church, Church Lane

#### Designation type(s): GII

Listed building ref(s): UID: 241471 List entry number: 1045692 Local: 4/5

BaR survey date(s): 25/05/2012

Condition: Very bad

Occupancy: Not applicable

Risk level: 1A – extreme risk

Ownership: Private



#### Description

Pair of chest tombs. Mid-19<sup>th</sup> century. Ashlar, with ashlar base and iron railings. Square plan. Tombs have moulded plinths and cornices and decorated traceried panels. Surrounding ornate cast iron railing in decorated style has pierced, traceried octagonal corner piers with cresting. To William Chappell and others. Designated: 4<sup>th</sup> December 1985.

#### **Reasons for risk status**

Structural failure, decay and material loss to ornate railings. Loose railings and cresting material amongst foliage and rested on tombs. Erosion to stone work and foliage growing through fabric.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

1A – no change.

## BaR: 11 Cottam

Church of Holy Trinity, Town Street

# Font half a metre east of south porch at Church of Holy Trinity



#### Description

Font half a metre east of south porch at Church of Holy Trinity. Font bowl. 14<sup>th</sup> century. Ashlar, octagonal. Carried on octagonal stem, with base inscribed 'Ancient font presented to Church by Archbishop .....', '1918', and with Vicar and Churchwardens' names. Designated: 4<sup>th</sup> December 1985.

#### **Reasons for risk status**

Removed from its base. Becoming green.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3A – no change.

Designation type(s): GII

Listed building ref(s): UID: 241498 List entry number: 1370089 Local: 6/32

BaR survey date(s): 30/05/2012

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private

## BaR: 12 Cuckney

## Dam at Cuckney School

**School Lane** 

#### Designation type(s): GII Cuckney CA

Listed building ref(s): UID: 241414 List entry number: 1045714

Local: 8/59

BaR survey date(s): 14/05/2007 18/06/2012

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Dam, consisting of sluice gates, walls, boat house and railings. 18<sup>th</sup> century, altered late 1872. Dressed coursed rubble, ashlar, iron and red brick. Ashlar and dressed coursed rubble wall extending 170 metres around the south, east and north sides of the mill pond. Terminating at the south in a red brick boat house. 4 sets of sluice gates to the east and west. The machinery inscribed "Kirkland Engineer Mansfield 1872". Iron railings extend intermittently around the east and south sides, these are decorated with alternate spikes and fleuron. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

Railings in poor condition and ironwork is corroding. Several finials missing.

#### **Relevant planning history**

Listed Building Consent granted in September 2007 to relocate fish guard and repair sluice (reference: 60/07/00005/L).

#### Previous risk level/change from 2004 BaR survey

3A – no change.

# 3 chest tombs in the Churchyard of the Church of St Giles

3 metres east of the chancel, Main Street

Designation type(s): GII

BaR: 13

Darlton

Listed building ref(s):

UID: 241445 List entry number: 1045727 Local: 3/5

BaR survey date(s): 17/09/2010

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

3 chest tombs. 3 metres east of the chancel, early to mid-19<sup>th</sup> century. 3 ashlar chest tombs enclosed within a rectangular iron compound. The northern most tomb to Mary is coffin shaped and is dated 1818, the central rectangular tomb to Mary Ann Newstead is dated 1845 and the similar southernmost tomb to Thomas Newstead is dated 1842. All are decorated with stylised crosses. Enclosing the tombs are decorative iron railings set upon a chamfered ashlar base. At each corner is a hollow iron pier decorated with blind and open tracery. Designated: 12<sup>th</sup> July 1985.

#### **Reasons for risk status**

Railings split, ironwork is corroding and finials lying on the ground. Ivy growth on tombs.

#### **Relevant planning history**

None.

Previous risk level/change from 2004 BaR survey

3A – no change.

Gatehouse Lodges and Gate

**Piers** 

## BaR: 14 Drakeholes

#### Wiseton

#### Designation type(s):

GII Wiseton & Drakeholes CA

## Listed building ref(s):

UID: 241199 List entry number: 1045046 Local: 5/115

#### BaR survey date(s):

24/06/2008 20/04/2011 25/10/2011

Condition: Poor

Occupancy: Partially occupied

Risk level: 3 – at risk

Ownership: Private



#### Description

Pair of lodges, early 19<sup>th</sup> century. Brick rendered, pyramidal slate roofs, single side wall stacks. Stone dressings, deep moulded eaves. Openings flanked by pilasters; matching corner pilasters. Square plan one storey one bay. Street front has single central glazing bar sash; gateway front has central 6 panelled door with rectangular overlight. East front has 3 bay round arched arcade with rendered square piers on stone plinths. Designated: 13<sup>th</sup> April 1977.

#### **Reasons for risk status**

Partially occupied, being used for storage in relation to small holding. Rear portico on south lodge completely lost, north lodge portico in parlous condition. Windows, doors and stucco render in poor condition, but vegetation cleared and roofs fully repaired with Council grant assistance in 2011.

#### **Relevant planning history**

Listed building consent granted for renovation works (ref: 56/10/0000/L).

#### Previous risk level/change from 2004 BaR survey

1 – improvement.

27

# Churchyard of Church of St Oswald **Group of 3 Headstones in**





BaR: 15

Dunham

18m south of the

chancel

#### Designation type(s): GIL

Listed building UID: 241451 List entry number: 1289459 Local: 4/11

BaR survey date(s): 16/12/2009 24/11/2011

Condition: Poor

Occupancy: Not applicable

**Risk level:** 3A – at risk

**Ownership**: Private



#### Description

Group of 3 headstones. Dated 1729, 1738 and 1731. Ashlar. Arched, rectangular headstone inscribed "Here lieth the body of Mary B....oll who departed this life March 7 1729 aged 60 years". To the right is a decorative arched rectangular headstone with decorative incised lines under the arch and inscribed "Here lieth the body of Robert the son of John and Mary Wills who departed this life February the 19 1738 aged 10 years". 2 metres to the right is the third arched rectangular headstone with inscription "Here lieth the body of Mary the wife of John Bacon who departed this life M.... 2. In the year of our Lord 1731.". Designated: 12<sup>th</sup> July 1985.

#### **Reasons for risk status**

Very eroded, inscriptions difficult to read. Lichen and greenery evident.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3A – no change.

## BaR: 16 Dunham

#### 12m north of the tower

## North gateway to Churchyard of Church of St Oswald



Listed building ref(s): UID: 241452 List entry number: 1045729 Local: 4/12

BaR survey date(s): 16/12/2009 24/11/2011

Condition: Fair

Occupancy: Not applicable

#### Risk level:

4A – vulnerable (buildings to watch)

Ownership: Church



#### Description

Gateway. 12 metres north of the church tower. Mid-19<sup>th</sup> century. Ashlar and iron. Central small iron gate flanked by single engaged columns with moulded capitals which support an ashlar overthrow with hood mould and central cross. The columns are attached to single small sloping ashlar walls. Designated: 12<sup>th</sup> July 1985.

#### **Reasons for risk status**

Some erosion of stone columns and underside of the ashlar overthrow. Extensive greening of stone.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

## BaR: 17 Dunham

## West gateway to Churchyard of Church of St Oswald

Ŏ

24m west of the tower, Main Street

#### Designation type(s): GII

Listed building ref(s): UID: 241453 List entry number: 1212606 Local: 4/13

BaR survey date(s): 16/12/2009 24/11/2011

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Church



#### Description

Gateway, west of the church tower. Mid-19<sup>th</sup> century. Ashlar and iron. Central small double iron gate flanked by single engaged columns with possible C14 foliate decorated capitals which support an ashlar overthrow with hood mould and central cross. Extending for one and a half metres and sloping down from the columns are single ashlar walls which are set on plinths. Designated: 12<sup>th</sup> July 1985.

#### **Reasons for risk status**

Significant erosion of stone columns and underside of the ashlar overthrow. Extensive greening of stone.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

## BaR: 18 East Markham

Church Lane, NG22 OSA

# Former Rectory (Honeysuckle House)



## Listed building ref(s):

UID: 419470 List entry number: 1223688 Local: 5/103

BaR survey date(s): 16/12/2009 19/06/2012

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership:

Private



#### Description

Rectory. Mid-19<sup>th</sup> century. Render over red brick. Ashlar plinth. Slate roof. 2 rendered gable stacks. Gables coped with ashlar. Single central blocked opening. Either side are single glazing bar sashes with 3 similar sashes above. To the rear are 2 storey wings. Designated: 28<sup>th</sup> February 1952.

#### **Reasons for risk status**

Broken windows, slipped roof slates and damaged/blocked rainwater goods. Some render removed with visible cracking to brick work. Vegetation is a problem on and around the house.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3 – no change.

## BaR: 19 Eaton

## **Eaton Hall International**

Great North Road, DN22 OPR

#### Designation type(s): GII

Listed building ref(s): UID: 419472 List entry number: 1267102 Local: 3/32

BaR survey date(s): 19/08/2008 7/08/2009

Condition: Fair

Occupancy: Occupied

Risk level:

5 – vulnerable (building to watch)

Ownership: Private



#### Description

House, now college. Early 19<sup>th</sup> century with later 19<sup>th</sup> century extension. White painted stucco. Slate roof, hipped to the left with bracketed cornice. 3 large stucco stacks to the rear. The left 5 bays are set on a plinth. 3 storeys, 8 bays. 4 stone steps set into a paved platform lead to the single storey projecting bay with doorway. Designated: 14<sup>th</sup> November 1985.

#### **Reasons for risk status**

Shabby appearance, with render flaking off and signs of defective rainwater goods. In need of maintenance. Unauthorised plastic windows and satellite dishes.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

5 – no change.

## BaR: 20 Gamston

## **Bramcote School**

#### **Rectory Lane**

#### Designation type(s): GII Gamston CA

# Listed building ref(s):

UID: 419844 List entry number: 1223924 Local: 3/50

#### BaR survey date(s):

25/06/2009 26/06/2012

Condition: Fair

Occupancy: Vacant

#### Risk level:

4 – vulnerable (building to watch)

Ownership: Private



#### Description

Former rectory, recently a school. Mid-18<sup>th</sup> century with early 19<sup>th</sup> century addition. Red brick. Plain tile roof. Single left gable, ridge and external right red brick stacks. Dentil eaves. Set on a brick plinth. 2 storeys plus garret, 6 bays. To the left and extending for 2 metres is a 19<sup>th</sup> century brick coped wall. To the rear are extensive modern additions, not included in the listing. Designated: 1<sup>st</sup> February 1967; amended 14<sup>th</sup> November 1985.

#### **Reasons for risk status**

Structurally sound, but lack of maintenance and vacant.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

## BaR: 21 Gringley

## Pigeoncote at Church Farm

Õ

**High Street** 

#### Designation type(s): GII Gringley CA

# Listed building ref(s):

UID: 241125 List entry number: 1156629 Local: 5/43

BaR survey date(s): 5/08/2009

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private



#### Description

A pigeoncote from the late 18th century, of square plan, built in brick with a pantile roof and tumbled brick coped gables. It has a central stable door flanked to each side by a single 20th century casement window. Above is a central close boarded door, and above again are four tiers of pigeonholes. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

Some maintenance work is needed to repair the roof and gutters. Small amounts of vegetation need to be removed from the eastern wall. The adjacent stables and granary, that were originally included in the listing, appear to have been demolished.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3 – no change.

## BaR: 22 Grove

**Main Street** 

# Almshouses



Designation type(s): GII

## Listed building ref(s):

UID: 241501 List entry number: 1212418 Local: 7/35

BaR survey date(s): 10/08/2009

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Private



#### Description

Almshouses. Early 18<sup>th</sup> century. Brick with steep pitched pantile roofs. First floor band. Single central ridge stack. Single storey plus garrets. 2 bays. Roof has cruck trusses. Main west front has central pair of doors in plain jambs, and beyond, single casements. Above, 2 small central leaded casements. Gables have, above, a single leaded Yorkshire sash. Designated: 4<sup>th</sup> December 1985.

#### **Reasons for risk status**

These almshouses are in a very serious condition. They are almost completely hidden by the mass of thick trees and vegetation that surround. The houses are on the verge of collapse, with large holes in the roof and serious damp problems in the brickwork. With no road access to this building, it is difficult to foresee a positive future for these almshouses.

#### **Relevant planning history**

None.

Previous risk level/change from 2004 BaR survey

1 – no change.

## BaR: 23 Holbeck

# Cartshed and attached outbuilding at Warrener's Farm

Holbeck Lane



#### Description

A cartshed, outbuilding and barn from the 18<sup>th</sup> century, all built of dressed coursed rubble stone. The cartshed is a single storey building of five bays with dressed coursed rubble piers, the right bay being part blocked with red brick. The rear wall has three buttresses. Attached to the right is a single storey, four bay outbuilding. The barn is two storeys, nine bays. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

The roof is sagging and uneven, in addition to the slipping of tiles and ridge tiles that have opened up holes in the roof. The masonry also needs pointing and some of the stone is bowing outwards where the roof is sagging. Vegetation is also a problem on one side where it is growing up the side of the building.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

1 – no change.

#### Designation type(s): GII Holbeck CA

# Listed building ref(s):

UID: 418452 List entry number: 1267526 Local: 7/93

BaR survey date(s): 11/08/2009

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Private
## BaR: 24 Holbeck

## Outbuildings opposite Woodhouse Hall

#### Worksop Road



#### Description

This range of late 18<sup>th</sup> and early 19<sup>th</sup> century agricultural buildings includes a barn, a cartshed and one outbuilding. They are built of coursed rubble, dressed coursed rubble with ashlar quoins and red brick. The buildings have tiled roofs and a mix of fenestration with some shuttered openings.. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

The conditions of the roofs on these buildings are very bad, some with slipped tiles and uneven rooflines, and others with large holes or portions of roof missing. The masonry also has large cracks in it and needs pointing. Many windows are unglazed and most gutters are broken. Vegetation is also a problem, both on and around the buildings.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3 – deteriorated.

#### Designation type(s): GII Holbeck CA

#### Listed building ref(s): UID: 419871 List entry number: 1223946 Local: 7/111

BaR survey date(s): 11/08/2009

Condition: Very bad

Occupancy:

Vacant

Risk level: 1 – extreme risk

Ownership: Private

## BaR: 25 Markham Moor

# Canopy to former petrol station

North of A1/A57 slip road



Listed building ref(s): List entry number: 1402678

BaR survey date(s): 30/06/2011

Condition: Fair

Occupancy: Vacant

#### **Risk level:**

4 – vulnerable (building to watch)

Ownership: Private



#### Description

The canopy is a hyperbolic paraboloid shell structure. It has sharp fins that point skywards while the sides sweep low towards the ground. Its form can be likened to a handkerchief, with two corners rising to apexes of 37 feet 4 inches above the ground, while the two opposite corners are only 5 feet above ground. At the dip in the centre, the height is 18 ft 6 in. The canopy is supported on its lower edges by four, simple concrete stanchions. The restaurant building does not have special interest and is excluded from the listing. Designated: 27<sup>th</sup> March 2012.

#### **Reasons for risk status**

The concrete canopy roof is showing signs of deterioration and requires some attention. Building is currently vacant.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 26 Mattersey

**Ranskill Road** 

# Cart shed 25 metres east of gingang at Mattersey Hill Farm



#### Description

This range of late 18<sup>th</sup> and early 19<sup>th</sup> century agricultural buildings includes a barn, a cartshed and one outbuilding. They are built of coursed rubble, dressed coursed rubble with ashlar quoins and red brick. The buildings have tiled roofs and a mix of fenestration with some shuttered openings. Designated: 27<sup>th</sup> November 1984.

#### **Reasons for risk status**

The cartshed is in poor condition with the ashlar columns badly eroded resulting in significant loss of their circumference. The roof and walls are showing signs of deterioration that may lead to structural collapse.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3 – no change.

#### Designation type(s): GII

Listed building ref(s): UID: 416975 List entry number: 1273784 Local: 3/95

BaR survey date(s): 2/10/2009 25/02/2010

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private

### BaR: 27 Misson

## Northfield House, railing and boundary walls

Station Road, DN10 6EW

Designation type(s): GII

## Listed building ref(s):

UID: 241153 List entry number: 1045074 Local: 1/71

BaR survey date(s): 25/08/2009 22/05/2012

Condition: Fair

Occupancy: Occupied

#### Risk level: 5 – vulnerable (building to watch)

Ownership: Private



#### Description

House, late C18, brick, partly rendered, with C20 pantile roof. 2 stone coped gables with kneelers, 2 gable stacks, 2 storeys, 3 bays. West front has central plain doorcase with half-glazed C20 door and stained glass overlight, flanked by single plain sashes. Above, 3 plain sashes. All openings have rubbed brick heads. C19 lean-to rear extension, brick with pantile roof. Outside, C19 cast iron spearhead railing with 2 gates. To north, brick boundary wall with stone coping, approx. 25 m long: to south, similar higher boundary wall approx. 75 M long. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

South boundary wall is misshapen some lateral movement. North boundary wall covered in undergrowth. Railings are rusting. Windows of house need repairing and repainting.

#### **Relevant planning history**

None.

Previous risk level/change from 2004 BaR survey

### BaR: 28 Misterton

## Misterton Station House and outbuildings

Gainsborough Road



#### Description

Misterton's former railway station was built in 1875. It is of gault brick with red brick, blue brick and stone dressings and has a slate roof. On either side are one storey lean-to buildings, of which the one to the right used to be the ticket office and toilet block. The former ticket office is of one bay and has a slate roof (of which the slates seems to be lost) with a single gable stack. To the right is the toilet block, flat roofed and also of one bay, with two segmental headed doors. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

The former ticket office and toilet block are in a very poor condition being partially overgrown and having lost their roofs.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

3 – no change.

#### Designation type(s): GII

## Listed building ref(s):

UID: 241162 List entry number: 1045077 Local: 6/78

BaR survey date(s): 7/03/2007 29/01/2010

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private

### BaR: 29 Misterton

# Number 7 and attached pigeoncote

**Gringley Road** 

Designation type(s): GII

Listed building ref(s):

UID: 241165 List entry number: 1045078 Local: 6/80

BaR survey date(s): 20/01/2009

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private



#### Description

Mid-18<sup>th</sup> century detached brick house with concrete tile roof. Central 20<sup>th</sup> century half glazed door surrounded by single plain sashes with segmental heads. Brick and stone coped gables and brick first floor band. Attached to the rear is an 18<sup>th</sup> century brick pigeoncote with pantile roof. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

The house requires maintenance, notably to the masonry, windows and gutters. The roof appears to be in a fair condition. The rear service wing, pigeoncote and other outbuildings require repair and maintenance. Evidence of spalled brick work and problems with vegetation. Slipped pantiles also evident. Crack in brickwork above first floor window header on south side of rear service wing.

#### **Relevant planning history**

None.

Previous risk level/change from 2004 BaR survey

## BaR: 30 Misterton

## Haxey Gate Bridge

Haxey Road

Designation type(s): GII

Listed building ref(s): UID: 241168 List entry number: 1302728 Local: 3/83

BaR survey date(s): 13/01/2009

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Road bridge, late 18<sup>th</sup> century. Ashlar with ashlar dressings. Single segmental arch with square imposts projecting. Ashlar parapet, rendered. Single square ashlar gatepier at north end. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

The stone parapet is in poor condition. Tree roots are a problem.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 31 Misterton

# Access bridge at pumping engine houses

Soss Road



Listed building ref(s): UID: 241178 List entry number: 1045082 Local: 3/94

BaR survey date(s): 29/01/2010 16/02/2011

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Access road bridge, c.1803, brick with stone coping, soffit and imposts. Single stilted segmental arch, curved brick parapet with stone coping, linked with boundary wall of south engine house. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

The bridge is covered in vegetation and the water channel is barely visible. Condition of brick work is a concern, notably where visible at tunnel entrance and on the parapets at roadway level.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 32 Nether Langwith

## Langwith Mill House

Langwith Mill Lane, NG20 9JF

Designation type(s): GII Nether Langwith CA

Listed building ref(s): UID: 419876 List entry number: 1224043 Local: 7/116

BaR survey date(s): 5/03/2010 16/03/2011

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Private



#### Description

House. Late 18<sup>th</sup> century, heightened early nineteenth century, with later extensions. Dressed coursed rubble with ashlar quoins. Slate roof with stone coped gables and dressed coursed rubble gable chimney stacks. Two and a half storeys, 5 bays. Central doorway with panelled door and overlight. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

The building is vacant. Although boarded up, the building has been broken into on a number of occasions, with lead and copper stolen. Roofs in very poor condition and water ingress is becoming an increasing problem. Evidence of fire damage in attached service wing.

#### **Relevant planning history**

Previous permission granted for change of use to a restaurant (ref: 64/88/00007/D).

#### Previous risk level/change from 2004 BaR survey

## BaR: 33 Ragnall

# Ragnall Hall and attached outbuildings

Main Street, NG22 OUR

#### Designation type(s): GII

#### Listed building ref(s): UID: 409383

List entry number: 1276446 Local: 4/59

BaR survey date(s): 3/10/2007 10/08/2009

Condition: Poor

Occupancy: Partially occupied

Risk level: 3 – at risk

Ownership: Private



#### Description

Ragnall Hall is a former country house, probably the seat of the Mellish family. It dates back to the early seventeenth century with early nineteenth century alterations. The farmhouse at the front of the hall dates from the 19th century and is of rendered red brick with a hipped slate roof. To the right is the steep gable and one mullion-and-transom-cross window of the early 17th century hall. The main parts of the old hall survive as storehouses. Designated: 28<sup>th</sup> February 1952.

#### Reasons for risk status

Hall and outbuildings showing signs of neglect. Farmhouse roof has been repaired in last 10-15 years, but roofs to hall and other outbuildings in poor condition. Farmhouse is currently being renovated, but other buildings vacant.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 34 Ragnall

## Barn at Ragnall Stables

Main Street, NG22 OUR

Designation type(s): GII

Listed building ref(s): UID: 409483 List entry number: 1233877 Local: 4/61

BaR survey date(s): 13/11/2007

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership:

Private



#### Description

The aisled barn at Ragnall Stables dates to about 1700 with 19th century alterations. It is of red brick and retains most of the original timber frame under its pantile roof. There is a single aisle to the east with the west side having a large doorway with wooden door. The interior has a purlin roof, six remaining main posts, wall plates and many other original timbers. Designated: 12<sup>th</sup> July 1985.

#### **Reasons for risk status**

The condition of this building has worsened considerably since it was last surveyed in 2003. The slipped pantiles have left holes in the roof. The brickwork is showing signs of cracking and the wooden door is in need of maintenance. A considerable amount of the guttering is also missing.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 35 Retford

## 26 & 28 Grove Street

**Grove Street** 

#### Designation type(s): GII Retford CA

Listed building ref(s): UID: 240920 List entry number: 1045178 Local: 1/118

BaR survey date(s): 20/04/2009 23/11/2011

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Private



#### Description

Early C19. 3 storeys in brick with pantile roof. 4 windows, 1 modern, the others hung sashes with glazing bars, brick voussoirs. 2 windows to ground floor and late C19 shop front. Moulded doorcase with door of 6 carved panels, blocked rectangular ornamental fanlight. Round-headed passage entry. Designated: 5<sup>th</sup> November 1976.

#### **Reasons for risk status**

Nos 26 and 28 have been neglected for a long period of time. Masonry is in a poor condition. Partial collapse in rear service wing/exposed roofs. Windows in poor condition. Rainwater goods defective. Pigeon infestation. No 24 is part of the same listing, but is in good condition/occupied.

#### **Relevant planning history**

Planning permission and listed building consent granted for mixed use redevelopment (refs: 01/11/00282 and 01/11/00283/L).

#### Previous risk level/change from 2004 BaR survey

## BaR: 36 Retford

## King Edward VII Grammar School

London Road

#### Designation type(s): GII Retford CA

#### Listed building ref(s): UID: 240932

UID: 240932 List entry number: 1045184 Local: 4/126

#### BaR survey date(s):

18/08/2006 6/08/2009 16/05/2012

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private



#### Description

Built in 1855 in a Tudor style, this school is made up of 1 and 2 storey blocks of red brick with ashlar dressings and Welsh slate roof. The walls are buttressed throughout. The windows are mullion and transom and a pointed tower sits above the central main door decorated with gargoyles, finials and the royal arms. Designated: 5<sup>th</sup> November 1976. Boundary wall to London Road listed separately.

#### Reasons for risk status

School vacated in 2007. Key problems include defective rainwater goods which is causing damp to run down the walls in places, resulting in discolouration, moss growth, efflorescence and spalling of the brick face. Some windows are broken, including a skylight. Vegetation is an increasing problem, already growing in the gutters and close around the base of the building.

#### **Relevant planning history**

None. In new ownership as of 2012.

#### Previous risk level/change from 2004 BaR survey

## BaR: 37 Retford

## The Church of St Alban



#### London Road

#### Designation type(s): GII Retford CA

## Listed building ref(s):

UID: 491538 List entry number: 1391188 Local: 888/0/10005

#### BaR survey date(s): 7/08/2008

18/04/2011

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Church



#### Description

Parish church built in 1902-31, initial design and eastern end by Charles Hodgson Fowler. Perpendicular in style, the church is built of limestone ashlar and plain tile roof. In the western corner is an octagonal spirelet with slate roof. Significant windows include a rose window in the north transept, 5-light east window in the chancel, 3-light east window in the Lady chapel, and clerestory windows along the nave. Designated: 30<sup>th</sup> September 2004.

#### **Reasons for risk status**

Church substantially damaged by fire in August 2008. Internal fabric destroyed, roof collapsed. No windows or rainwater goods. Shell of church survives. Walls scaffolded and site fenced off.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

### BaR: 38 Retford

## 23 & 24, Market Square

#### The Square (Market Place)

Designation type(s): GII Retford CA

## Listed building ref(s):

UID: 240954 List entry number: 1045150 Local: 1/31

#### BaR survey date(s): 24/11/2008 23/01/2011

Condition: Fair

Occupancy: Vacant

#### **Risk level:**

4 – vulnerable (building to watch)

#### Ownership: Privato

Private



#### Description

3 storeys in red brick with Welsh slate roof with end stacks. Pedimented centre breaks forward with rusticated pilasters, which occur also at the ends of the building. Small parapet. Moulded cornice and rusticated ground floor. 3 windows, shouldered and shaped stucco surrounds to lst and 2nd floors, cills on tabs. 1st floor windows of 3 lights. Only the marks remain of cornices and pediments. Designated: 5<sup>th</sup> November 1976.

#### **Reasons for risk status**

Vacant building. Stucco plaster to main elevation failing, with sections falling off. Broken sash windows to front.

#### Relevant planning history

Planning permission and listed building consent granted in 2007 for change of use of ground floor to café/restaurant and residential uses above (refs: 01/07/00390/R and 01/07/00391/L).

#### Previous risk level/change from 2004 BaR survey

## BaR: 39 Retford

## Former stables to West Retford Hall

**Rectory Road** 

Designation type(s): GII Retford CA

## Listed building ref(s):

UID: 240978 List entry number: 1179117 Local: 3/15A

#### BaR survey date(s): 20/05/2009 9/05/2012

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Local authority



#### Description

18<sup>th</sup> century stable court, altered. 2 storeys in brick with Welsh slate and pantile roofs. One side has 4 windows and door and 2 windows with glazing bars and segmental-arched head above various windows, including 2 with Gothick glazing bars. Round-headed passage entry. Opposite side includes 2 carriage entries. 3rd side backs onto brick garden wall, with later storage extensions. Designated: 14<sup>th</sup> September 1949.

#### **Reasons for risk status**

Currently vacant. Roofs in poor condition, with partial collapse in west carriage structure. Vegetation is increasingly a problem. Broken windows.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 40 Rockley

## Ice-house at Rockley House

Mill Lane

#### Designation type(s): GII

Listed building ref(s): UID: 420420 List entry number: 1224429 Local: 5/91

BaR survey date(s): January 2004

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Ice-house. Late 18<sup>th</sup> century interior, 19<sup>th</sup> century exterior. Red brick. Pantile roof. Dentil eaves. Doorway with ashlar lintel. Steps lead down to a moulded brick archway and further down to a doorway with depressed arch. Interior has 3 arched niches and a barrel roof. Designated: 14<sup>th</sup> November 1985.

#### **Reasons for risk status**

The roof is in need of repair. Vegetation is a problem.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 41 Serlby

#### Serlby Park, Serlby Lake Drive

#### Designation type(s): GII

Listed building UID: 416656 List entry number: 1273915 Local: 2/58

BaR survey date(s): January 2004

Condition: Very bad

Occupancy: Not applicable

**Risk level:** 1A – extreme risk

**Ownership:** Private



Garden seat in

**Serlby Park** 

#### Description

Garden seat. Late 18<sup>th</sup> century. Red brick, ashlar and stucco. Pantile roofs with stone coped parapets. Single storey, three bays, with impost bands. The central, slightly projecting bay has a Serliana with brick piers and ashlar imposts. The top of the arch is flanked by single, small, rectangular panels. Either side the single walls with sloping parapets and single kneelers have stuccoed bands continuing from the imposts. Designated: 27<sup>th</sup> November 1984.

#### **Reasons for risk status**

Collapsed north pier. Cracks in south pier; evidence of subsidence.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

**Serlby Hall** 

Tennis pavilion at

### BaR: 42 Serlby

#### Serlby Hall Drive

#### Description

The late 18<sup>th</sup> century tennis pavilion in the grounds of Serlby Hall is of red brick and ashlar with hipped slate roofs. It is a two storey, three bay building with a slightly recessed two storey, two bay wing to the left and a single storey, single bay wing to the right. The windows were glazing bar sashes in arched openings. It is also referred to as 'The Barracks' as it was used by soldiers during the 20<sup>th</sup> century. Designated: 14<sup>th</sup> November 1985.

#### **Reasons for risk status**

The building is vacant. The roof covering is now totally absent and the timbers are decimated. The structure is unstable with some scaffolding used to support the walls. Windows are broken and there is vegetation growth inside.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

1 – no change.

#### Designation type(s): GII

Listed building ref(s): UID: 241081 List entry number: 1370366 Local: 2/53

BaR survey date(s): January 2004

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Private

## BaR: 43 Shireoaks

## Ha-Ha at Shireoaks Hall

#### Thorpe Lane

#### Designation type(s):

GII Shireoaks CA Shireoaks Hall P&G SM

### Listed building

UID: 241216 List entry number: 1370409 Local: 1/8

BaR survey date(s): 9/08/2007

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private



#### Description

Early 18<sup>th</sup> century. 100 metres to south west of house. Fine irregularly coursed squared rubble with ashlar coping. Approximately 150 metres long. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

Heavy vegetation cover. Roots are causing a problem. Some areas of partial stonework collapse. Mining subsidence a potential problem.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 44 Styrrup

## Yews Farmhouse

Main Street, DN11 8NA

#### Designation type(s): GII

Listed building ref(s): UID: 420566 List entry number: 1266718 Local: 1/164

BaR survey date(s): 6/06/2008 2/06/2011

Condition: Good

Occupancy: Vacant

#### Risk level:

5 – vulnerable (building to watch)

### Ownership:

Private



#### Description

16<sup>th</sup> century cottage. Refronted late eighteenth century. Red brick front on a coursed rubble plinth, probable complete timber frame. Pantile roof, two red brick gable stacks. 2 storeys, 3 bays. Central doorway, panelled door with moulded wooden surround. To the top right of the doorway is a small glazing bar pointed arched fixed light. Between this and the doorway is a wooden post rising from the plinth to the eaves, there is a similar post at the left angle. Designated: 12<sup>th</sup> April 1985.

#### **Reasons for risk status**

Building is vacant. It is, however, watertight and in good condition. The ground floor windows are boarded up, the roof has been repaired.

#### **Relevant planning history**

Listed Building Consent granted for alterations to the single storey off-shot (ref: 66/11/00008/L). Comprehensive schedule of works agreed.

#### Previous risk level/change from 2004 BaR survey

### BaR: 45 Torworth

Blyth Road, DN22 8PB

# Stable block, barn and attached outbuildings at the Mantles



#### Description

Stable block, barn and attached buildings. Late C18. Ashlar and red brick with pantile roofs. Stable block has central 2 1/2 storey single bay flanked by single 2 storey 5 bay wings. Ashlar central bay with stone coped gable and kneelers to the front and hipped roof to the rear. 1st and 2nd floor bands, tall elliptical carriage arch with keystone, arched opening in the attic and 2 round tie plates. The flanking wings each of brick with ashlar quoins have dentillated eaves and are set on an ashlar plinth. Designated: 1<sup>st</sup> February 1967; amended 27<sup>th</sup> November 1984.

#### Reasons for risk status

Section of roof is deteriorating and there is vegetation growth on walls.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

Designation type(s): GII

## Listed building ref(s):

UID: 417783 List entry number: 1222617 Local: 2/130

BaR survey date(s): 16/10/2012

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private

## Pigeoncote at Brookside Farm

## BaR: 46 Treswell

#### Green Lane, DN22 OEN

Designation type(s): GII

Listed building ref(s): UID: 409492 List entry number: 1233883 Local: 1/70

BaR survey date(s): 7/08/2009

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private



#### Description

Pigeoncote, now store. Mid-18<sup>th</sup> century. Red brick. Pantile roof with crowstepped gables. Dentil eaves band with a further raised brick eaves band which extends around the gable walls. 2 storeys plus garret. West wall has a doorway with wooden door under a segmental arch. Above, breaking the band, is an arched panel with entrances for pigeons and above is a single owl opening. The east wall has a similar doorway and single owl opening. Interior has nesting boxes and perches. Designated: 12<sup>th</sup> July 1985.

#### **Reasons for risk status**

Roof and masonry are deteriorating with a small hole in the roof and a lost ridge tile. Masonry over the small side window showing signs of fracture. Otherwise shows signs of general neglect.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 47 Wallingwells

Wallingwells House Lane

#### Designation type(s): GII

## Listed building

UID: 420432 List entry number: 1224552 Local: 4/173

#### BaR survey date(s): January 2004

Condition: Very bad

Occupancy: Not applicable

Risk level: 1A – extreme risk

Ownership: Private No image available

Castle garden and kitchen

garden at Wallingwells Hall

#### Description

Garden wall with 4 projecting pavilions at the angles. Mid C18. Coursed rubble with ashlar dressings. Quadrangle plan, standing at the head of a quarry, with an embattled coursed rubble wall to the north, east and west. At the north east and north west corners are single storey pavilions, each with a single pointed arched entrance in their north walls. At the south east corner is a 3 storey embattled pavilion. The west side, first floor, opens out into the garden, with single central pointed arched window, flanked by single, taller, narrower, similar arches. In the south wall is a single pointed arched window opening. Designated: 14<sup>th</sup> November 1985.

#### **Reasons for risk status**

In very poor condition. In need of extensive repair.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

Walled garden to

Wallingwells Hall

## BaR: 48 Wallingwells

Wallingwells House Lane



Listed building ref(s): UID: 420438 List entry number: 1266865 Local: 4/179

BaR survey date(s): January 2004

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Private No image available

#### Description

Walled garden. Coursed rubble with quoins and ashlar coping. Quadrangle plan. Doorway to the east with wooden door, ashlar surround and keystone. Interior has on the north wall, near the base, a stone with incised cross marking where Dame Margaret Dourant, the second prioress, is reputedly buried. The south west corner has a coursed rubble lean-to with exterior concrete lintel. The east wall has a single stone block with worn decorative moulding. Designated: 14<sup>th</sup> November 1985.

#### **Reasons for risk status**

Poor condition. In need of repairs.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey



#### Relevant planning history

very overgrown and fenced off.

None.

1 – extreme risk

**Ownership**:

Private

Previous risk level/change from 2004 BaR survey

### BaR: 50 Wiseton

## Ice-house at Wiseton Hall

Spring Lane

Designation type(s): GII Wiseton & Drakeholes CA

Listed building ref(s): UID: 241208 List entry number: 1045051 Local: 7/124

BaR survey date(s): 29/01/2010

Condition: Very bad

Occupancy: Not applicable

Risk level: 1A – extreme risk

Ownership: Private



#### Description

Ice-house, circa 1800. Brick doorway with damaged segmental head, partly rendered. Interior, brick passage with 2 door slots; circular saucer domed brick ice chamber, partly rendered. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

Unused and in very poor condition. Trees are growing out of the roof and causing damage to the structure. Partial masonry collapse.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 51 Wiseton

#### **Chesterfield Canal**

#### Designation type(s):

GII Wiseton & Drakeholes CA

## Listed building ref(s):

UID: 241196 List entry number: 1156858 Local: 5/126

#### BaR survey date(s): 29/01/2010

Condition: Poor

Occupancy: Not applicable

Risk level: 3A – at risk

Ownership: Unknown



Lady's Bridge

#### Description

Ornamental canal bridge, late C18 and C19. Brick rendered, with ashlar dressings. Single stilted segmental arch with ashlar soffits with mask keystones; ashlar coping carrying ornamental C19 cast iron railing. Octagonal abutments and railing piers with octagonal ashlar caps. Designated: 23<sup>rd</sup> November 1984.

#### **Reasons for risk status**

Corroding railings, excessive ivy growth and loss of render. One pier has collapsed.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

### BaR: 52 Worksop

#### Bridge Street, S80 1DL

## **93 Bridge Street**

Designation type(s): GII Worksop CA

Listed building ref(s): UID: 241229 List entry number: 1156199 Local: 7/22

BaR survey date(s): 29/09/2008 2/03/2009

Condition: Fair

Occupancy: Occupied

#### **Risk level:**

5 – vulnerable (building to watch)

Ownership: Private



#### Description

House, now shops. Early C19. Brick, stuccoed, with hipped slate roof. Stone sills, stucco quoins to right only, plain timber eaves, 3 side wall stacks. 4 storeys, 4 bays. Facade has 2 C20 shopfronts, and above 4 plain sashes on each floor, those on the fourth floor being smaller. Later C19 rear wing, brick with slate roof, for industrial use. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

Gutters full of debris and vegetation.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 53 Worksop

## 106, 108 & 110 Bridge Street

Bridge Street, S80 1HT

Designation type(s): GII Worksop CA

Listed building ref(s): UID: 241234 List entry number: 1156225 Local: 7/27

BaR survey date(s): 24/08/2009

Condition: Poor

Occupancy: Partially occupied

Risk level: 3 – at risk

Ownership: Private



#### Description

Originally a town house, 17<sup>th</sup> century, 1745 and refronted in mid-19<sup>th</sup> century. Rendered and colourwashed. 5 bay 20<sup>th</sup> century shopfront, carriageway with another 20<sup>th</sup> century shopfront. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

This building is partially occupied at ground floor only. There is no internal access other than by ladder to 106. Externally the gutters are blocked. Window repairs needed to front and rear elevations. The eaves to front are damaged. Pigeon roosting is a problem. Render is failing.

#### **Relevant planning history**

Planning and Listed Building Consent granted in 2008 for demolition and extensions to 108-110 Bridge Street to become part of the adjacent hotel.

#### Previous risk level/change from 2004 BaR survey

### BaR: 54 Worksop

## 124 Bridge Street (Nail Bar)

#### Bridge Street, S80 1HT

#### Designation type(s): GII

Worksop CA

#### Listed building ref(s): UID: 241241 List entry number: 1045064

Local: 7/34

#### BaR survey date(s): 27/09/2011 25/05/2012

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private



#### Description

House, now shops and offices. 1760. Brick with hipped pantile roof and ashlar dressings. Brick first floor band, coped parapet and decorative iron balustrade. 3 storeys plus attics, 3 bays. Front has, to left, carriage entrance in setback bay; to right, modern shop front flanked by single Doric columns. In return angle, decorative rainwater head inscribed 'JE 1760'. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

Lead stolen from front roof parapet and dormer damaged, resulting in water ingress and damage to internal plaster. Currently vacant.

#### **Relevant planning history**

Planning and Listed Building Consent granted in 2012 for residential conversion above shop.

#### Previous risk level/change from 2004 BaR survey

## BaR: 55 Worksop

#### **Drinking Pit Lane**

#### Designation type(s): GII Welbeck Abbey P&G

Listed building ref(s): UID: 241271 List entry number: 1156540

Local: 3/62A

BaR survey date(s): 24/08/2009

Condition: Poor

Occupancy: Vacant

Risk level: 3 – at risk

Ownership: Private



Old Toll Bar Lodge

#### Description

Toll house, early C19. Coursed squared stone with graduated slate roof. Ashlar dressings, plinth, deep eaves, 3 grouped central diagonally-set stacks. Single storey, 3 bays, cross plan. Main east front has central projecting bay with studded door, flanked by single casements. Similar rear elevation. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

This building is unoccupied and located in an isolated place within woodland. Lead and tiles have been removed from the main roof and a temporary roof covering has been installed.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 56 Worksop

## Sewage pumping station and chimney

Bracebridge, High Hoe Road, S80 2DS

#### Designation type(s): GII Worksop CA

### Listed building

ref(s): UID: 241288 List entry number: 1370404 Local: 3/79

BaR survey date(s): 26/11/2004 25/04/2008 14/02/2011

Condition: Fair

Occupancy: Vacant

#### Risk level:

4 – vulnerable (building to watch)

#### Ownership:

Private



#### Description

Sewage pumping station. 1881. Italian Romanesque style. Brick/ashlar with gault and blue brick dressings, hipped slate roof. Chamfered coping, sill band, round arched corbel table, brick eaves. Single storey on basement, 5 bays. All windows are tall round headed iron frame casements. Chimney, 3 stages, square plan, ashlar base with recessed panels and moulded coping, blind arcaded string course, corbel table and moulded ashlar eaves band. Designated: 16<sup>th</sup> December 1976.

#### **Reasons for risk status**

Vacant. Fairly recent maintenance work has left the roof and much of the masonry in good condition. The windows are unglazed, which could cause deterioration. In a stable condition.

#### **Relevant planning history**

Planning permission and Listed Building Consent granted in 2004 to erect 3 storey extensions and carry out alterations to provide 24 flats.

#### Previous risk level/change from 2004 BaR survey

1 – improved.

## BaR: 57 Worksop

#### Lodge Farm Lane, S80 3DL

## Barn and stable at Lodge Farm



Listed building ref(s): UID: 241289 List entry number: 1156602 Local: 3/80

BaR survey date(s): 4/08/2009

Condition: Poor

Occupancy: Partially occupied

Risk level: 3 – at risk

Ownership: Private



#### Description

Barn and stable. Early C19. Coursed squared rubble with hipped pantile roofs. Ashlar dressings, quoins and eaves band. Various breathers. Barn, 2 storeys, 4 bays, has central bay with 3 small hatches, flanked by pairs of barn doors with segmental heads and timber lintels. Lower stable range, to east, 2 storeys, 3 bays, has 4 hatches, 2 in blocked doorways with segmental heads. To right, mounting block. Above, 3 pitch holes and 2 paired breathers. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

These buildings are in need of maintenance. A substantial amount of vegetation (mainly ivy) covers much of the walls and roof, hiding some windows. Some tiles have slipped leading to the formation of holes in the roof. The masonry would benefit from re-pointing.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 58 Worksop

## Drive wall and gate piers at Worksop Manor

Mansfield Road

### Designation type(s): GII

Listed building ref(s): UID: 241295 List entry number: 1156628 Local: 3/85

BaR survey date(s): January 2004

Condition: Poor

Occupancy: Not applicable

#### Risk level: 3A – at risk

Ownership: Private



#### Description

Pair of boundary walls. 18<sup>th</sup> century. Coursed squared rubble with ashlar dressings. Intermediate buttresses, and rusticated gate piers with pyramidal caps at intervals. Approx. 200 metres long. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

Sections of masonry in poor condition, notably to the drive walls where there has been partial collapse.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey

## BaR: 59 Worksop

196 & 198 Newcastle Avenue, S80 1NN

#### Designation type(s): GII Worksop CA

#### Listed building ref(s): UID: 241304 List entry number: 1370074 Local: 3/95

BaR survey date(s): 11/08/2009

Condition: Very bad

Occupancy: Vacant

Risk level: 1 – extreme risk

Ownership: Private



Mill Cottages and

Outbuilding

#### Description

Pair of cottages. Early 19<sup>th</sup> century. Coursed squared rubble and brick dressings with pantile roof. 2 storeys, 2 bays, one gable stack. West front has paired central doors with chamfered jambs and lintels, that to right with segmental head; flanked by single 3 light casements with segmental heads. At rear, collapsed remains of single storey lean-to extension. Designated: 24<sup>th</sup> January 1984.

#### **Reasons for risk status**

This building has been seriously neglected. The roof has almost completely collapsed and the building is closely surrounded by trees and vegetation. No doors remain and windows are unglazed. The location of the building next to a busy road island affects the desirability of the building. The site is fenced off.

#### **Relevant planning history**

None.

#### Previous risk level/change from 2004 BaR survey
# BaR: 60 Worksop

#### **Old Gateford Road**

# Ice-house to rear of Gateford Farmhouse

Designation type(s): GII Old Gateford CA

## Listed building ref(s): UID: 241278 List entry number: 1156569 Local: 1/69

BaR survey date(s): 6/01/2009

Condition: Poor

Occupancy: Vacant

Risk level: 3A – at risk

Ownership: Private



#### Description

Ice-house. Late eighteenth century. Coursed squared rubble and brick with ashlar dressings. West entrance has brick stairs with ashlar lintel and inner doorway. East entrance has rubble ramp and similar lintel. Rubble lined square chamber with segmental brick vault, approx. 5 metres each way. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

Unused and neglected. Vegetation is causing problems and the structure is vulnerable to vandalism and litter (potential fire risk). Isolated location in woodland/scrub.

#### **Relevant planning history**

Permission granted to redevelop land to west included a scheme for repairing the ice house as part of public realm/landscaping proposals (ref: 02/11/00026).

#### Previous risk level/change from 2004 BaR survey

3A – no change.

# BaR: 61 Worksop

# **The French Horn Hotel**

#### 15, Potter Street

#### Designation type(s): GII Worksop CA

# Listed building ref(s):

UID: 502732 List entry number: 1392412 Local: 400/0/10012

## BaR survey date(s): 6/01/2009 28/08/2012

Condition: Fair

Occupancy: Vacant

#### Risk level:

4 – vulnerable (building to watch)

Ownership: Private



#### Description

Public house. 1906 with late C20 internal alterations. Built for the Sheffield brewers Hooson Bros. by Frederick Hopkinson. Red brick with terracotta and faience dressings, banding and decoration, tall brick chimneys with moulded cappings, and a tile roof covering with crested ridges and elaborate finials to gablets. Designated: 25<sup>th</sup> February 2008.

#### **Reasons for risk status**

This building is vacant, with all ground floor windows boarded up. The roof has been fully repaired and stone work cleaned during summer 2011.

#### **Relevant planning history**

Draft urgent works notice issued to owner in summer 2009; repairs undertaken. Discussions regarding the future of the building are in progress.

#### Previous risk level/change from 2004 BaR survey

n/a – new entry.

# BaR: 62 Worksop

# **Telephone Exchange**

Queen Street, S80 2AN



#### Description

Telephone exchange. 1939 with later extensions. Taken out of service 1979 and converted to a museum. Red brick with Westmorland slate hipped roof with a single brick chimney stack. Single storey. Main, north street façade has projecting wing to left with single cross casement window with the words TELEPHONE and EXCHANGE in raised lettering to either side. To right a 3-light casement window. East front has 6 windows, with three 2-light cross casements to left and two 3-light cross casements with a further 2-light window to right. West front has recessed entrance doorway and beyond a later extension. Designated: 26<sup>th</sup> February 2002.

#### **Reasons for risk status**

This building is vacant, with all windows boarded up.

#### **Relevant planning history**

None.

Previous risk level/change from 2004 BaR survey

n/a – new entry.

Designation type(s): GII Worksop CA

## Listed building ref(s): UID: 488495

UID: 488495 List entry number: 1359555 Local: 400/0/10009

## BaR survey date(s): 8/12/2008

24/08/2009

Condition: Fair

Occupancy: Vacant

#### Risk level:

4 – vulnerable (building to watch)

Ownership: Private

# BaR: 63 Worksop

# **Quorn House**

50 Watson Road, S80 2AA

Designation type(s): GII Worksop CA

Listed building ref(s): UID: 241346 List entry number: 1045772 Local: 8/137

BaR survey date(s): 2/11/2010

Condition: Fair

Occupancy: Vacant

**Risk level:** 

4 – vulnerable (building to watch)

Ownership: Private



#### Description

House, partly converted from former industrial building, now offices. Late C18. Brick, colourwashed, with ashlar dressings and hipped and pyramidal slate roofs. First floor band, dentillated eaves, 3 ridge stacks, single roof ventilator. 2 storeys, 5 bays. Irregular facade has, to right, recessed bay containing pilastered doorcase with moulded capitals and hood, with plaque above inscribed 'Quorn House'. Flanked to left by 2 glazingbar sashes with bracketed sills and hoods, and beyond, doorway with segmental head; to right, one similar glazing bar sash. Above, 2 small and 3 standard glazing bar sashes. Designated: 1<sup>st</sup> April 1985.

#### **Reasons for risk status**

This building is vacant and in need of basic repairs.

#### Relevant planning history

None.

Previous risk level/change from 2004 BaR survey

n/a – new entry.



# 3. Structures removed from the Register

## 3. Structures removed from the Register

Buildings and structures are removed from the BaR when they have been repaired and renovated to the point of being structurally sound, wind and weathertight. In addition, they must be in use or occupied to the extent that they are being well maintained. Buildings in the process of being repaired but not in use may still be vulnerable and therefore remain at risk.

The following entries in this section detail which buildings have been removed from the previous BaR publication and why. Where possible, photographs are included to demonstrate the current condition of the building.

In addition to the above, buildings which are not statutorily listed have been removed from the list as per the methodology set out in section one of this document<sup>18</sup>.

Grade I and II\* listed buildings are identified on the national register<sup>19</sup>. Entries in this listing category on the previous BaR therefore have been removed.

#### Clayworth Methodist Church, Town Street, Clayworth

Grade II, Clayworth CA List entry number: 1289620



The chapel following conversion.

Reason(s) no longer at risk:

Converted to a house in 2005/2006. Occupied and in good condition.

<sup>&</sup>lt;sup>18</sup> On the previous BaR, Nether Langwith Mill and 11 Eldon Street were included for their local interest value. These have been removed from this Register but due to their prominence in conservation areas, their condition will be identified in any associated Appraisal Management Plan.

<sup>&</sup>lt;sup>19</sup> English Heritage publishes and monitors the *Heritage at Risk Register* for the East Midlands: <u>http://www.english-heritage.org.uk/caring/heritage-at-risk/</u>. Note that Grade II listed buildings that are also Scheduled Monuments or active places of worship may be included on the national register.

Date of inspection: 22/03/2006 Barn at Manor Farm, Woodcoates Road, Darlton Grade II List entry number: 1370100



Before

After

Reason(s) no longer at risk:

Converted to residential accommodation 2008/2009. Occupied and in good condition.

Date of inspection: 14/05/2009

#### Ice-house at the gatehouse lodges, Drakeholes

Grade II, Wiseton & Drakeholes CA List entry number: 1156865



The ice-house entrance and interior.

Reason(s) no longer at risk:

Foliage and debris removed from steps, walls and floor. In good condition and being maintained.

Date of inspection: 20/04/2011 High Brecks Farmhouse, High Brecks Farm Lane, East Markham Grade II List entry number: 1223682



Before

After

Reason(s) no longer at risk:

Fully repaired and renovated between 2008 and 2010. Occupied, in good condition and being maintained.

Date of inspection: 11/07/2011

#### Pigeoncote at Northfield Farm, Everton Sluice Lane, Everton

Grade II, Everton CA List entry number: 1370390



Before

After

Reason(s) no longer at risk:

Substantially rebuilt and converted to residential accommodation in 2007. Occupied and in good condition.

Date of inspection: 6/09/2012

## Gringley Windmill, Mill Hill, Gringley on the Hill Grade II

List entry number: 1156678



Before

After

Reason(s) no longer at risk:

Repaired and converted to office/business usage. Wind and weathertight, occupied and in good condition.

Date of inspection: 7/08/2009

#### Pigeoncote at Manor Farm, Harwell Lane, Harwell

Grade II List entry number: 1302803



Before

After

#### Reason(s) no longer at risk:

Pigeoncote totally demolished for safety reasons, allegedly following accidental structural collapse. Prosecution considered, but no further action taken. No structure remains.

Date of inspection: 7/12/2009 Barn at Grange Farm, Main Street, Harworth Grade II List entry number: 1045716



Before

After

Reason(s) no longer at risk:

Converted to residential during 2007/2008 and fully repaired. Occupied and being maintained.

Date of inspection: 5/09/2009

#### Barn 4 metres east of post office, Main Street, Harworth

Grade II List entry number: 1045717



Before

After

Reason(s) no longer at risk:

Converted to residential during 2009/2010 and fully repaired. Occupied and being maintained.

Date of inspection: 15/03/2010

#### Pair of cottages at Mattersey Hill Farm, Ranskill Road, Mattersey Grade II List entry number: 1239193



The cottages before and during repairs

Reason(s) no longer at risk:

Fully repaired during 2010 and re-established as residential usage. Occupied and being maintained.

Date of inspection: 29/03/2010

### Outbuildings to rear of house, 13 High Street, Misterton

Grade II List entry number: 1156764



Before

After

Reason(s) no longer at risk:

Converted to residential during 2006/2007 and fully repaired. Occupied and being maintained.

Date of inspection: 23/11/2010

#### **Cowhouse and stable at Yew Tree Farm, Main Street, North Leverton** Grade II

List entry number: 1234468



Before

After

Reason(s) no longer at risk:

Converted to residential during 2006/2007 and fully repaired. Occupied and being maintained.

Date of inspection: 14/04/2009

## Barn at Yew Tree Farm, Main Street, North Leverton

Grade II List entry number: 1276145



Before

After

Reason(s) no longer at risk:

Converted to residential during 2006/2007 and fully repaired. Occupied and being maintained.

Date of inspection: 14/04/2009 **12 Chapelgate, Retford** Grade II, Retford CA List entry number: 1045204



Following renovation.

Reason(s) no longer at risk:

Renovated and fully repaired during 2006/2007 (part of THI grant scheme). Occupied and being maintained.

Date of inspection: 2/07/2007

**24 Moorgate, Retford** Grade II, Retford CA List entry number: 1045160



Before

After

Reason(s) no longer at risk:

Substantially demolished in 2011 and subsequently rebuilt through an enforcement notice. Soon to be occupied.

Date of inspection: 31/01/2012 **37 Moorgate, Retford** Grade II, Retford CA List entry number: 1045154



Before

After

Reason(s) no longer at risk:

Renovated and fully repaired during 2011 and now in good condition. Occupied and being maintained.

Date of inspection: 31/01/2012

39 & 41 Moorgate, Retford

Grade II, Retford CA List entry number: 1302138



Before

After

Reason(s) no longer at risk:

Renovated and fully repaired during 2011 and now in good condition. Occupied and being maintained.

Date of inspection: 31/01/2012

## Other structures removed from the BaR:

Building/structure	Designation	List entry no	Reason for removal from BaR		
Church of St James, Haughton	Grade II*, SAM	1267085	Addressed through national BaR.		
Langwith Mill, Cuckney Road, Nether Langwith	Nether Langwith CA	n/a	Not a principal listed building (although associated with adjacent mill house which remains on the BaR). Addressed through CA Appraisal & Management Plan.		
Gateway and walls from Manor Farm, Rampton	Grade I	1276407	Addressed through national BaR.		
Gateposts to Bolham Hall, Bolham Lane, Retford	Formerly grade II	n/a	De-listed 24/03/2010.		
Arch at Serlby Park, Serlby	Grade II*	1224495	Addressed through national BaR.		
Shireoaks Hall, Thorpe Lane, Shireoaks	Grade II*	1370408	Addressed through national BaR.		
East stable at Shireoaks Hall, Thorpe Lane, Shireoaks	Grade II*	1045054	Addressed through national BaR.		
West stable at Shireoaks Hall, Thorpe Lane, Shireoaks	Grade II*	1045055	Addressed through national BaR.		
Church of St Helens, South Wheatley	Grade I, SAM	1216694	Addressed through national BaR.		
Gatepiers to Sutton Manor, Sutton cum Lound	Grade II	1239883	In good condition and being maintained.		
11 Eldon Street, Tuxford	Tuxford CA	n/a	Not a listed building. Building is a positive structure in CA. Its		

			condition is a factor in CA's at risk status. Addressed through CA Appraisal & Management Plan.		
Grotto, Grotto Walk, Welbeck	Grade II	1266631	Foliage cleared. In good condition and being maintained.		
Cow sheds, Winnings Road, Welbeck	Grade II	1223925	Repaired and in good condition. Being maintained.		
West Lodge, Winnings Road, Welbeck	Grade II	1267515	Repaired and in good condition. Being maintained.		
South Lodge at Forest Hill House, Blyth Road, Worksop	Grade II	1370410	Repaired and in good condition. Being maintained.		
Worksop Priory Gatehouse, Cheapside, Worksop	Grade I	1045028	Addressed through national BaR.		
Cloister wall at Priory Church, Priorswell Road, Worksop	Grade I	1156758	Addressed through national BaR.		

## Commentary

The total number of entries on the 2012 BaR is 63 Grade II structures. This is 6.5% of all Grade II listed buildings in Bassetlaw. This is a reduction from the 2004 BaR which had 91 entries (accounting for 8.6% of all listed buildings in the District).

The change can be attributed to a number of factors, including a change in methodology (higher grade listed buildings are no longer included in the local BaR for example), owner repair strategies and the implementation of relevant planning applications and Listed Building Consents.



# 4. Reducing the risks

## 4. Reducing the risks

Bassetlaw District Council is committed to reducing the number of listed buildings at risk within the area<sup>20</sup>. This will be challenging given the number of assets on the Register and the different kinds of risk they face.

Local authorities have a primary role in protecting the historic environment. The creation of a local heritage at risk register is the first step in tackling neglected buildings in order to assess and monitor the scale of the problem and prioritise resources and action.

The Register entries contained within this document are varied. Understanding why these heritage assets are at risk and what issues need to be addressed to allow their removal from the Register will often require a bespoke approach and solution. There are, however, some general approaches that are relevant to all assets at risk, and resolving cases will require working in close partnership with owners and other relevant organisations and partners<sup>21</sup>. Advice and understanding are essential.

Maintenance of heritage assets is essential to prevent them becoming at risk. It is also important to prevent those that are already at risk from decaying further and that the cost of their repair and consolidation does not escalate further. Buildings, for instance, decay rapidly when left empty. Avoiding vacancy through short-term lets or schemes that provide protection through residential occupation are low-cost ways of maintaining buildings until permanent solutions can be found<sup>22</sup>.

Local authorities can also take action to secure the preservation of historic buildings through the use of statutory notices<sup>23</sup>. It is essential that the Council makes best use of their powers to secure buildings at risk, to 'stop the rot' and prevent the costs escalating beyond the point where it is economic to repair. For this reason, the Council will use English Heritage's revised guidance *Stopping the Rot* (2011) as a general framework for taking action to save historic buildings.

<sup>&</sup>lt;sup>20</sup> This commitment is set out in Strategic Objective 9 of the LDF Core Strategy and its delivery is monitored through the Annual Monitoring Report (AMR). This approach is consistent with English Heritage's National Heritage Protection Plan (2011-2015) and the priorities for the East Midlands.

<sup>&</sup>lt;sup>21</sup> For example, working in partnership with other organisations such as local and national amenity societies, including English Heritage, SAVE Britain's Heritage, the Society for the Protection of Ancient Buildings, the Georgian Group, The Victorian Society, The Twentieth Century Society, the Council for British Archaeology and the Ancient Monuments Society

<sup>&</sup>lt;sup>22</sup> English Heritage has published guidance for owners on options for maintaining vacant buildings (*Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing* (2011)).

<sup>&</sup>lt;sup>23</sup> To help local authorities, English Heritage runs grant schemes to underwrite a proportion of the irrecoverable costs involved in serving Urgent Works Notices and Repairs Notices.



# 5. Additional information



## 5. Additional information

#### **Useful contacts**

Conservation Team Bassetlaw District Council Queen's Buildings Potter Street Worksop S80 2AH Telephone: 01909 533191 E-mail: <u>oliver.scott@bassetlaw.gov.uk</u>

English Heritage East Midlands Region 44 Derngate Northampton NN1 1UH Telephone: 01604 735400 E-mail: <u>eastmidlands@englishheritage.org.uk</u>

Conservation Team Nottinghamshire County Council Trent Bridge House Fox Road West Bridgford Nottingham NG2 6BJ Telephone: 0300 500 80 80 E-mail: <u>heritage@nottscc.gov.uk</u>

Notts Building Preservation Trust Minster Chambers Church Street Southwell Nottinghamshire NG25 0HD Telephone: 01636 819555 E-mail: <u>mail@nbpt.co.uk</u>

SAVE Britain's Heritage 70 Cowcross Street London EC1M 6EJ Telephone: 020 7253 3500 E-mail: office@savebritainsheritage.org

The Society for the Protection of Ancient Buildings 37 Spital Square London E1 6DY Telephone: 020 7377 1644 E-mail: <u>info@spab.org.uk</u>

The Georgian Group 6 Fitzroy Square London W1T 5DX Telephone: 087 1750 2936 E-mail: <u>info@georgiangroup.org.uk</u>

The Victorian Society 1 Priory Gardens London W4 1TT Telephone: 020 8994 1019 E-mail: <u>admin@victoriansociety.org.uk</u>

The Twentieth Century Society 70 Cowcross Street London EC1M 6EJ Telephone: 020 7250 3857 E-mail: website@c20society.org.uk

The Council for British Archaeology 66 Bootham York Y030 7BZ Telephone: 01904 671 417 E-mail: webenguiry@archaeologyUK.org

#### Grants

Grants might be available for the repair and conservation of designated heritage assets at risk.

Where appropriate, these grants are likely to only be offered for urgent repairs or other work to prevent loss or damage to important architectural features. Grant aid might also be available for project development work, including the preparation of specialist reports and studies, as a basis for repair or future management of heritage at risk.

#### Potential grant sources:

Listed Buildings at Risk grant Bassetlaw District Council http://www.bassetlaw.gov.uk/planning\_and\_building/conservation\_heritage/grant s.aspx

Grants for Historic Buildings, Monuments and Designed Landscapes *English Heritage* <u>http://www.english-heritage.org.uk/professional/funding/grants/grants-</u> <u>available/hbmdl/</u>

#### **Publications and guidance**

English Heritage has produced the following publications relating to heritage at risk, including:

Buildings at Risk: a New Strategy (1998)

Heritage Works: the use of Historic Buildings in Regeneration (2006)

Constructive Conservation in Practice (2008)

*Conservation Principles, Policies and Guidance for the Sustainable Management of the Historic Environment (2008)* 

Heritage at Risk: Conservation Areas (2009)

*Caring for Places of Worship 2010* – a report on the condition of England's listed places of worship and the needs of the congregations (2010)

Heritage at Risk 2010 - report

Caring for Historic Graveyard and Cemetery Monuments (2011)

Stopping the Rot: A Guide to Enforcement Action to Save Historic Buildings (2011)

Vacant Historic Buildings: An Owner's Guide to Temporary Uses, Maintenance and Mothballing (2011)

Heritage at Risk 2012 - national report and summary leaflet for the East Midlands

Heritage at Risk Register 2012 – detailed listings for the East Midlands (Grade I and II\* listed buildings only).

#### Heritage at risk on the web

For more information on tackling listed buildings at risk in Bassetlaw, visit our website at:

http://www.bassetlaw.gov.uk/planning and building/conservation heritage/listed buildings at risk.aspx.

To find out more about the national programme for tackling heritage at risk, visit:

www.english-heritage.org.uk/risk.

Here you will find an interactive database providing detailed information on all heritage sites at risk nationally.

For further information about the different classes of designated heritage assets, including listed buildings, scheduled monuments, registered parks and gardens, registered battlefields and protected wreck sites visit:

www.english-heritage.org.uk/heritageprotection.

Details of all nationally designated historic places in England are available in one place on the National Heritage List for England online database:

http://list.english-heritage.org.uk.

English Heritage also provides on-line advice and guidance to owners and managers of sites through the Historic Environment Local Management (HELM) website: <u>www.helm.org.uk</u>.

#### **Contact us**

For further advice on issues relating to the historic environment:

**Conservation Team** Planning Policy and Conservation **Bassetlaw District Council** Queen's Buildings Potter Street Worksop Nottinghamshire S80 2AH

Tel: 01909 533191 or 533484

For help and advice on submitting Planning Permission, Conservation Area Consent or Listed Building Consent applications:

Planning Administration Tel: 01909 533264 or 01909 534430

If you need any help understanding any of our documents, please contact us on 01909 533427.

BaR no.	Name of structure	Location	LB ref	2004 risk level	2012 risk level	Change from 2004
01	Pigeoncote, Pear Tree Farm	Beckingham	1370368	3 - at risk	4 - vulnerable	Improved
02	Memorial to Joseph Dymond	Blyth	1273833	3A - at risk	3A - at risk	No change
03	Gateway to Blyth Hall	Blyth	1238970	3A - at risk	3A - at risk	No change
04	Milestone on Sheffield Road	Blyth	1239142	3A - at risk	3A - at risk	No change
05	Road bridge, Meadow Lane	Bothamsall	1391658	n/a - new entry	3A - at risk	n/a
06	Lavin's Cottage	Carlton	1206347	3 - at risk	3 - at risk	No change
07	Barns at North House	Carlton	1280211	n/a - new entry	3 - at risk	n/a
08	Wigthorpe House	Carlton	1206458	n/a - new entry	1 - extreme risk	n/a
09	Wall at Manor Farm	Church Laneham	1276573	1A - extreme risk	4A - vulnerable	Improved
10	Pair of chest tombs	Clarborough	1045692	1A - extreme risk	1A - extreme risk	No change
11	Font at Church	Cottam	1370089	3A - at risk	3A - at risk	No change
12	Dam at Cuckney School	Cuckney	1045714	3A - at risk	3A - at risk	No change
13	3 chest tombs at Church	Darlton	1045727	3A - at risk	3A - at risk	No change
14	Gatehouse lodges	Drakeholes	1045046	1 - extreme risk	3 - at risk	Improved
15	3 headstones at Church	Dunham	1289459	3A - at risk	3A - at risk	No change
16	North gateway at Church	Dunham	1045729	n/a - new entry	4A - vulnerable	n/a
17	West gateway at Church	Dunham	1212606	n/a - new entry	3A - at risk	n/a
18	Former rectory	East Markham	1223688	3 - at risk	3 - at risk	No change

#### Summary table of listed buildings at risk

19	Eaton Hall	Eaton	1267102	5 - vulnerable	5 - vulnerable	No change
20	Bramcote School	Gamston	1223924	n/a - new entry	4 - vulnerable	n/a
21	Pigeoncote at Church Farm	Gringley	1156629	3 - at risk	3 - at risk	No change
22	Almshouses	Grove	1212418	1 - extreme risk	1 - extreme risk	No change
23	Cartshed, Warrener's Farm	Holbeck	1267526	1 - extreme risk	1 - extreme risk	No change
24	Barns at Woodhouse Hall	Holbeck	1223946	3 - at risk	1 - extreme risk	Worse
25	Canopy to former petrol station	Markham Moor	1402678	n/a - new entry	4 - vulnerable	n/a
26	Cartshed, Mattersey Hill Farm	Mattersey	1273784	3 - at risk	3 - at risk	No change
27	Wall at Northfield House	Misson	1045074	n/a - new entry	5 - vulnerable	n/a
28	Misterton Station House	Misterton	1045077	3 - at risk	3 - at risk	No change
29	7 Gringley Road	Misterton	1045078	n/a - new entry	3 - at risk	n/a
30	Haxey Gate Bridge	Misterton	1302728	n/a – new entry	3A - at risk	n/a
31	Access bridge, pumping station	Misterton	1045082	3A - at risk	3A - at risk	No change
32	Langwith Mill House	Nether Langwith	1224043	n/a - new entry	1 - extreme risk	n/a
33	Ragnall Hall	Ragnall	1276446	3 - at risk	3 - at risk	No change
34	Barn at Ragnall Stables	Ragnall	1233877	3 - at risk	3 - at risk	No change
35	26 & 28 Grove Street	Retford	1045178	1 - extreme risk	1 - extreme risk	No change
36	King Edward VII School	Retford	1045184	n/a - new entry	3 - at risk	n/a
37	Church of St Alban	Retford	1391188	n/a - new entry	1 - extreme risk	n/a
38	23 & 24 Market Square	Retford	1045150	n/a - new entry	4 - vulnerable	n/a
39	Stables to West Retford Hall	Retford	1179117	n/a - new entry	3 - at risk	n/a
40	Ice-house at Rockley House	Rockley	1224429	3A - at risk	3A - at risk	No change
41	Garden seat at Serlby Park	Serlby	1273915	1A - extreme risk	1A - extreme risk	No change
42	Tennis pavilion, Serlby Hall	Serlby	1370366	1 - extreme risk	1 - extreme risk	No change
43	Ha-ha at Shireoaks Hall	Shireoaks	1370409	3A - at risk	3A - at risk	No change
44	Yews Farmhouse	Styrrup	1266718	n/a - new entry	5 - vulnerable	n/a
45	Stable block at The Mantles	Torworth	1222617	n/a - new entry	3 - at risk	n/a
46	Pigeoncote, Brookside Farm	Treswell	1233883	3 - at risk	3 - at risk	No change
47	Castle garden at Wallingwells Hall	Wallingwells	1224552	1A - extreme risk	1A - extreme risk	No change
48	Walled garden at Wallingwells Hall	Wallingwells	1266865	3A - at risk	3A - at risk	No change
49	Camelia House	Welbeck	1224847	1 - extreme risk	1 - extreme risk	No change
50	Ice-house at Wiseton Hall	Wiseton	1045051	1A - extreme risk	1A - extreme risk	No change
51	Lady's Bridge	Wiseton	1156858	3A - at risk	3A - at risk	No change
52	93 Bridge Street	Worksop	1156199	n/a - new entry	5 - vulnerable	n/a
53	106-110 Bridge Street	Worksop	1156225	n/a - new entry	3 - at risk	n/a
54	124 Bridge Street	Worksop	1045064	n/a - new entry	3 - at risk	n/a
55	Old Toll Bar Lodge	Worksop	1156540	n/a - new entry	3 - at risk	n/a
56	Bracebridge pumping station	Worksop	1370404	1 - extreme risk	4 - vulnerable	Improved
57	Barn at Lodge Farm	Worksop	1156602	3 - at risk	3 - at risk	No change
58	Drive wall, Worksop Manor	Worksop	1156628	3A - at risk	3A - at risk	No change
59	196-198 Newcastle Avenue	Worksop	1370074	1 - extreme risk	1 - extreme risk	No change
60	lce-house, Gateford Farmhouse	Worksop	1156569	3A - at risk	3A - at risk	No change
61	The French Horn Hotel	Worksop	1392412	n/a - new entry	4 - vulnerable	n/a
62	Telephone Exchange	Worksop	1359555	n/a - new entry	4 - vulnerable	n/a
63	50 Watson Road	Worksop	1045772	n/a - new entry	4 - vulnerable	n/a
		•				





Bassetlaw-Serving North Nottinghamshire Designed and printed by Bassetlaw District Council Printing Unit